

How to do

Teleservice TSA-II Modem from Siemens on VIPA 100V, 200V, 300V

The Teleservice TSA-II Modem from Siemens is actually not supported by CPU´s 100 V, 200V and 300V. Version Date 12.12.2006, Firmware: V3.87

Reason: These CPU´s don´t support the MPI auto protocol.

Solution: MPI-settings of the TSA-II modem
switch baudrate of MPI to 187,5 kBit/s

Change in Teleservice-Software: Menu: Extra

- adapter- settings
 - o net-typ: MPI
 - o Baudrate: 187,5 kbit/s

